

Torres Rojas, Genara

FOI #14763

From: fkblaw39broadway@yahoo.com
Sent: Friday, March 14, 2014 2:34 PM
To: Duffy, Daniel
Cc: Torres Rojas, Genara; Van Duyne, Sheree; American, Heavyn-Leigh
Subject: Freedom of Information Online Request Form

Information:

First Name: Michael
Last Name: Beatty
Company: Feldman, Kronfeld & Beatty
Mailing Address 1: 42 Broadway
Mailing Address 2: 19th Floor
City: New York
State: NY
Zip Code: 10004
Email Address: fkblaw39broadway@yahoo.com
Phone: 212-425-0230
Required copies of the records: Yes

List of specific record(s):

1 Inspection reports for the 42nd Street Bus Terminal for one year prior to and including January 2, 2014 of the area about Stairway B, third floor, specifically limited to the tile flooring of the pedestrian walking area abutting the curb. 2 Repair records of said area from January 2, 2013 to present. 3 Video recordings of the aforesaid area recording images between 12:45pm and 1:15pm on January 2, 2014. 4 Photographs depicting the aforesaid area as it existed for the period December 2, 2013 through and including January 2, 2014.

THE PORT AUTHORITY OF NY & NJ

FOI Administrator

June 6, 2014

Mr. Michael Beatty
Feldman, Kronfeld & Beatty
42 Broadway, 19th Floor
New York, NY 10004

Re: Freedom of Information Reference No. 14763

Dear Mr. Beatty:


This is in response to your March 14, 2014 request, which has been processed under the Port Authority's Freedom of Information Code (the "Code", copy attached) for Request for copies of the following records following records: 1. Inspection reports for the 42nd Street Bus Terminal for one year prior to and including January 2, 2014 of the area about Stairway B, third floor, specifically limited to the tile flooring of the pedestrian walking area abutting the curb. 2 Repair records of said area from January 2, 2013 to present. 3 Video recordings of the aforesaid area recording images between 12:45pm and 1:15pm on January 2, 2014. 4 Photographs depicting the aforesaid area as it existed for the period December 2, 2013 through and including January 2, 2014.

Material responsive to your request and available under the Code can be found on the Port Authority's website at <http://www.panynj.gov/corporate-information/foi/14763-C.pdf>. Paper copies of the available records are available upon request.

Certain material responsive to your request is exempt from disclosure pursuant to exemption (5) of the Code.

Please refer to the above FOI reference number in any future correspondence relating to your request.

Very truly yours,


Daniel D. Duffy
FOI Administrator

Attachment

STRUCTURAL INTEGRITY INSPECTION PROGRAM
INSPECTION CONDITION REPORT

Facility P.A.B.T.

Pg 1 of 3

Routine No. 4605 Field Temp. 80° Weather ### Scheduled MMMS 0134827-1

Description Southwing Suburban Bus level 3 Inspected By: S.R. Insp. Date 5/31/13

Item No.	Degree	Deficiency	Measure-ment	Element	Location	work Order #	Comments
1	critical	cracked	4'	Bricks	outbound lane COR. WALL		RT Struct.
2	Severe	rust	6X10X 13'	Box tube	" "		RT Struct
3	o/s	clogged	6" dia	Roadway DRAIN	" "		RT Plumbing
4	critical	impac damaged	1"	conduite & BOX	" "		RT Elect
5	heavy	loose, hanging rip	6"	pipe insulation	How gate 234 red line		RT USM possible ACM
6	heavy	rust		utility supports	low bound LANE (AC plant)		RT USM Elect
7	heavy	impac damage		" "	Numerous AC plant		hangers missing
8	critical	possible ACM		pipe insulation	C-30 ceiling		RT USM
9	critical	broken	12x12	glass block	Stair C Numerous		RT Struct
10	safety	missing	13 of 17		AC plant		RT Struct

SI d. J. Romano
INSPECTOR

Reviewed MS
MAINTENANCE UNIT SUPERVISOR

STRUCTURAL INTEGRITY INSPECTION PROGRAM
INSPECTION CONDITION REPORT

Facility P.A.B.T.

Pg 2 of 3

Routine No. 4605 Field Temp. 60 Weather Clear Scheduled MMMS 0134829-1

Description Southwing Suburban Bus level 3 Inspected By: J.R. Insp. Date 5/31/13

Item No.	Degree	Deficiency	Measure-ment	Element	Location	work Order #	Comments
11	minor	broken	22" x 6 x 6	tiles	col. 23-K off loadway		BT struct
12	safety item	broken	12x12	glass block	col 23-K Star B		BT struct
13	critical	impar damage	③ 4x2	duct s	col. K-20-21 cellina		BT as m / struct
14	minor	missing	4" x 10'	Expansion cover	col 16-K wall		BT struct
15	minor to severe	broken concrete			col-K numerals median divider		BT struct
16	severe	impar damage	0' x 3'	chip down cabinet	terward inbound lane		
17	severe	separated	3' x 1'	duct	col C-28 gate 205		BT as m / struct
18	heavy	impar damage		corner frame	gate 205		BT struct
19	O/S	clogged		drain	gate 204-205 roadway		BT Plumbing
20	Small	buildup		concrete debris	col A-19		

SI d. J. Romano
INSPECTOR

Reviewed MS

MAINTENANCE UNIT SUPV

